



Maintenance and Accelerator Support

RHIC Run 12

Major Maintenance Items for tomorrow:

- RHIC polarimeters
- E-lens phase shifter supply connection
- Uranium and other development and tests in the injectors.
- OPPIS Maintenance completed Monday- available for development etc..





Scheduling and planning:

- No access to Booster.
- AGS access limited, 0700-0900hrs.
- Tunnel access begins at 0600hrs.
- Reminder: 6 o'clock tunnel access: CA Access only: Enhanced Work Plan.
- Meeting here at 1430hrs for details.



Schedule:

- 0600hrs: Begin RHIC access, AGS LOTO.
- 0700hrs: AGS access, LINAC maintenance begins.
- 0900hrs: LINAC on for BLIP, Booster restoration and NSRL setup.
- 1100hrs: Restore LINAC and Booster for NSRL, begin BLIP restoration, begin AGS studies.
- 1200hrs: NSRL Running (LINAC protons).
- 1300hrs: RHIC sweeps begin.
- 1600hrs: RHIC tunnel secured, power supply testing in RHIC.
- 1700hrs: RHIC recovery with beam.



ACCELERATOR
ACCESS
Timetable


0600HRS

Begin
Polarimeter
work

Access Key

	Restricted Access
	Controlled Access
	No Access

LINAC
LTB
Booster





ACCELERATOR
ACCESS
Timetable


0800HRS

RHIC
Access
Underway

Access Key

	Restricted Access
	Controlled Access
	No Access

LINAC
LTB
Booster






ACCELERATOR ACCESS Timetable

1300HRS

Begin RHIC
Sweeps

Access Key	
<div></div>	Restricted Access
<div></div>	Controlled Access
<div></div>	No Access

LINAC
LTB
Booster





ACCELERATOR
ACCESS
Timetable


1600HRS

Tunnel
Sweeps
Complete

Access Key

	Restricted Access
	Controlled Access
	No Access

LINAC
LTB
Booster





ACCELERATOR
ACCESS
Timetable

1700HRS

RHIC
Restotation

Access Key

	Restricted Access
	Controlled Access
	No Access

LINAC
LTB
Booster

